

Rotovac	E-2500H
	heater page of 5
Enduro	
2-2 vac motor (parallel)	500 psi
H39	
oct2012	120V

#1

manual re-set button at thermostat

heater break-down

Note: auto re-set and no more manual re-set button at thermostat model after 02/2011

